

```

# At time 20 rst=0 load=1 enab=1 cnt_in=10101 cnt_out=10101
# At time 30 rst=0 load=1 enab=1 cnt_in=01010 cnt_out=01010
# At time 40 rst=0 load=1 enab=1 cnt_in=11111 cnt_out=11111
# At time 50 rst=1 load=1 enab=1 cnt_in=11111 cnt_out=00000
# At time 60 rst=0 load=1 enab=1 cnt_in=11111 cnt_out=11111
# At time 70 rst=0 load=0 enab=1 cnt_in=11111 cnt_out=00000
# TEST PASSED

```

