

## ASHUGANJ POWER STATION COMPANY LIMITED | DOCUMENT NO.: SF-AUX-34 | | REVISION NO.: 00 | | FORMS | EFFECTIVE DATE: 19/03/2018

TITLE: TROUBLE REPORT

PAGE: 1 OF 1

## TROUBLE REPORT

**Unit No./System:** 450 MW CCPP(North)

1. T.R. No. : 895 Date: 07-Feb-20 Time: 01:00 PM

2. Equipment: Shell-2 Location: Fuel gas perfomance h

3. Name of the Reporting Person: Shimul Golder Designation: Sub-Assistant Engineer

4. Description of Trouble:

Fuel gas perfomance heater shell-2 inlet pipe line found water leakage.

Please take necessary action.

5. Referred to: Executive Engineer (Mechanical

Sub-Assistant Engineer

Executive Engineer (Shift)

Shift Charge Engineer

## Copy to:

- 01. CE/Project Director, 450 MW CCPP, North, APSCL.
- 02. SE (MMD, EMD, Operation), 450 MW CCPP, North, APSCL
- 03. XEN (Operation) 450 MW CCPP, North, APSCL.