

Task 1 (Software Selection): Choose a BIM tool, create STUDIO and MEETING, and export the model as IFC4.

Task types

1
Single-Software
Execution
(Base capability)




2
Software Selection
(+ software choice)

3
Vision-Guided
Modeling
(+ drawings)

4
Design Optimization
(+ objectives)

5
Cross-Software
Coordination
(+ multiple applications)

6
Open-Environment
Engineering
(+ open environment)



Task 2 (Cross-Software Coordination): Build a finned heat plate in AutoCAD and SolidWorks, then analyze it in Abaqus.

