## Lab 6

- 1- Write a C program using Timer to generate a 1000 Hz PWM signal (square wave) on PORTB.5 with 50% Duty cycle, Using Polling (don't Use Interrupt).
  - a. Then examine the frequency using the oscilloscope.
  - b. Make it 70% Duty cycle.
  - c. Make it 90% Duty cycle.
  - d. Make it 20% Duty cycle.

• Information about Duty Cycles.