




$K_p = 30$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.0000$




K_d para junta 1




$K_p = 30$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.5236$



K_d para junta 2



$K_p = 30$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.5236$



K_d para junta 3

