





$K_p = 10$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.0000$




K_d para junta 1



$K_p = 10$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.5236$



$K_p = 10$ $K_d = \text{Amortecimento Crítico}$ $q_0 = 0.5236$



K_d para junta 3

