




ITEM	PART NUMBER	DESCRIPTION	QTY
1	QT-00243	SUPPORT BRACKET	2
2	QT-00257	TROUGH COPPER TRANSITION, 3000A	4
3	559680	ISO LOW VOLTAGE INS, 3/8-16 X 2"lg.	2
4	559694	ISO LOW VOLTAGE INS., 3/8-16 x 3"lg.	6
5		FLEXIBLE BRAID NEMA 2 HOLE	12
6		3/8-16 SET SCREW, 1"lg	3
7		3/8-16 SET SCREW, 1.50"lg	4
8		CIRCULAR WASHER, 3/8	2
9		LOCK WASHER, 3/8	2
10		HEX BOLT, 3/8-16 UNC - 1 L.	2
11		CIRCULAR WASHER, 1/2	96
12		LOCK WASHER, 1/2	48
13		HEX NUT, 1/2-13 UNC	48
14		HEX BOLT, 1/2-13 UNC - 2.25 L.	32
15		HEX BOLT, 1/2-13 UNC - 2.75 L.	16

NOTES: UNLESS OTHERWISE SPECIFIED.

1. TORQUE VALUES:
3/8-16 HARDWARE: 26ft-lbs
1/2-13 HARDWARE: 64ft-lbs

ALL DIMENSIONS ARE IN INCHES					PO BOX 1170 439 NC HWY 55 E MOUNT OLIVE, NC 28365	
DRAWN	J.Brown	DATE	2/8/2024			
CHECKED	J.Stevens	DATE	2/8/2024			
PROPRIETARY AND CONFIDENTIAL			DESCRIPTION			
THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF GOSHEN ENGINEERING LLC ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF GOSHEN ENGINEERING LLC IS PROHIBITED.			TROUGH TRANSITION W/FLEXIBLE BRAID, 3000A			
			DWG. NO.			
			QT-A00076			
SHEET SIZE		B	REV	0	SHEET 1 of 1	

QT-A00076.dwg
SHOP DRAWING FOR INTERNAL GOSHEN ENGINEERING AND SUBCONTRACTOR USE ONLY. THIS IS NOT INTENDED FOR CUSTOMERS OR END USERS.