



Distance Verification Markers – Test Lab Mode


Place these markers at known distances to verify calibration accuracy



ID 10 – Place at 0.50m from origin



ID 11 – Place at 1.00m from origin



ID 12 – Place at 1.50m from origin