


Production rate columns: evaluations of the curve function $f(t_i, \theta)$ at every period. The uncertainty is elementwise and should NOT be summed.



Cumulative production columns: properly summed production uncertainty using Monte Carlo simulations.

