
Production rate columns: evaluations of the curve function $f(t_i, \theta)$ at every period. The uncertainty is elementwise and should NOT be summed.
production
forecasted_production
forecasted_production_P10
forecasted_production_P50
forecasted_production_P90
0
1
2
3
Cumulative production columns: properly summed production uncertainty using Monte Carlo simulations.
cumsum(production)
cumulative_production
cumulative_production_P10
cumulative_production_P50
cumulative_production_P90
0
100
200
300
400
500
600
1980
1985
1990
1995
2000
2005
2010
2015
2020
2025