


SAFETY FIRST Isolate the circuit, verify absence of voltage, support the busbar and use suitable PPE.

Qualified personnel only

STEP 01

ALIGNMENT



ALIGN THE ELEMENT ENDS

Bring the two GL busbar elements together. Keep both sections level and align the conductors and housing before joining.

CHECK: Ends and conductors correctly aligned



STEP 02

JOINT PLATE + FIXINGS



FIT AND SECURE THE JOINT PLATE


Position the GL joint plate correctly and insert all fixing screws. Tighten the screws evenly to secure the connection.

CHECK: Joint plate fully seated and secured



STEP 03

COMPLETED JOINT



CHECK THE COMPLETED JOINT

Confirm the joint plate is fully seated and the connection is secure before energising the system.

CHECK: Joint secure with no visible gap



FINAL VERIFICATION



Elements are aligned and the GL joint plate is fully seated.



All fixing screws are installed and tightened evenly.



Support hanger spacing is maintained at 1500-2000 mm.