Original Picture



Intertek Testing Services (Tianjin) Ltd.
No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China
天津华苑新技术产业园区桂苑路7号 邮编 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Attention is drawn to the terms and conditions printed

NUMBER : TSNT01461499

Applicant : Shangyi (Tianjin) Fire Retardent Plastic Products Co., Ltd. Date : Jan 17, 2022

Attn : Gao Shukai

Sample Description As Declared :

No. Of Sample	:	One
Fibre Content	:	-
Material	:	Anti-Fired Foam
Finishing	:	-
End Uses	:	-
Colour	:	White
Style No.	:	-
Order No./PO No.	:	-
Buyer's Name	:	-
Agent's Name	:	-
Manufacturer's Name	:	-

Date Received/Date Test Started : Jan 11, 2022

Tests Conducted:

As Requested By The Applicant, For Details Refer To Attached Page(S)

Conclusion:

On The Basis Of The Tests Carried Out As Described, It Is The Opinion Of This Laboratory That The Foam Filling Material Of The Sample Would Meet The Requirements Of Schedule 1 Part I Of The Furniture And Furnishings (Fire)(Safety)Regulations 1988(As Amended).

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.

Patrick Gong
General Manager

Intertek Testing Services (Tianjin) Ltd.
No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China
天津华苑新技术产业园区桂苑路7号 邮编 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Attention is drawn to the terms and conditions printed

Tests Conducted:

1. Flammability Test (BS 5852 Part 2:1982, Crib Test):

BS 5852: Part 2: 1982 As Modified By Schedule 1 Part I (Ignitability Test For Polyurethane Foam In Slab Or Cushion Form) Of The Furniture And Furnishings (Fire) (Safety) Regulations 1988 (As Amended) And Using The Cover Fabric Detailed Below.

THe Tests Were Carried Out Using A 220g/m^2 Flame Retardant Polyester Fabric Which Deviates In Part From The Specification Stated In Schedule 1 Part 1 Of The Regulations. Although This Fabric Does Not Fully Meet The Specification Laid Down In The Regulations This Was Regarded As Having No Significant Effect On The Test

THe Following Test Results Relate Only To The Ignitability Of The Combination Of Upholstery Composites Under The Particular Conditions Of Test; They Are Not Intended As A Means Of Assessing The Full Potential Fire Hazard Of The Materials In Use.

Criterion Of Ignition: Ignition Source 5 - Crib.
Conditioning : 72 Hours Indoor Ambient And At Least 16 Hours Of 20±5°C, 50±20% Relative Humidity.
Testing Atmosphere : 15-30°C, 20-70% Relative Humidity
Performance Requirement : Clause 4.1-4.2 Of BS 5852 Part 2:1982

Test Result:

Progressive Smoldering Failure		1st Test	Retest
(A)	Any Composite That Produces Externally Detectable Amounts Of Smoke, Heat Or Glowing 60 Minutes After Ignition Of The Crib;	No	No
(B)	Any Composite That Displays Escalating Combustion Behaviour;	No	No
(C)	Any Composite That Smoulders Until It Is Essentially Consumed Within The Test Duration;	No	No
(D)	Any Composite That Smoulders To The Extremities Of The Specimen Viz Upper Or Lower Margins, Either Side Or To Its Full Thickness, Within The Duration Of The Test;#	Yes	Yes
(E)	Any Composite That, On Final Examination, Shows Evidence Of Charring Other Than Discolouration, More Than 100 mm In Any Direction Apart From Upwards From The Nearest Part Of The Original Position.#	Yes	Yes

Intertek Testing Services (Tianjin) Ltd.
No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China
天津华苑新技术产业园区桂苑路7号 邮编 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Attention is drawn to the terms and conditions printed

Tests Conducted:

Flammability Test(Cont'd)

Flaming Failure		1st Test	Retest
(A)	Any Composite That Continues To Flame For More Than 10 Minutes After The Ignition Of The Crib;	No	No
(B)	Any Composite That Displays Escalation Combustion Behaviour;	No	No
(C)	Any Composite That Burns Until It Is Essentially Consumed Within The Test Duration;	No	No
(D)	Any Composite On Which Any Flame Front Reaches The Lower Margin, Either Side Or Passes Through The Full Thickness Of The Specimen Within The Duration Of The Test.#	Yes	Yes

Resultant Mass Loss	1st Test	Retest
	42g	44 g

Foam	Ignition Source	Time To Extinction After Placement Of Ignition Source			
Test No.		Flaming Ceased Time		Smoking Ceased Time	
		Min	Sec	Min	Sec
1	5	3	16	5	27
Retest	5	3	31	5	43
Ignitability Performance Index		P5			

Remark : YES = Was Observed
NO = Was Not Observed
= If Failure Against The Criteria And Provided That The Resultant Mass Loss Was Less Than 60 g The Foam Pass The Ignitability Test

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

Intertek Testing Services (Tianjin) Ltd.
No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China
天津华苑新技术产业园区桂苑路7号 邮编 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Attention is drawn to the terms and conditions printed