

Photo: starboard sugar scoop, April 2023.



Surface rash on the outside corner of the starboard sugar scoop following the impact described on page 1. No hull penetration or water intrusion. Repaired at St. Augustine Marine Center.