COPPER & BRASS

HPb59-1

MATERIAL / REFERENCE CONDITION

Brass

Typical applications Turned inserts, connectors and threaded fittings

Material type	Brass
Condition / reference grade	Specify extruded or drawn condition
Manufacturing	Turning · milling
Reference data	Cu 57.0-60.0%; Pb 0.8-1.9%; Fe <= 0.5%; Zn balance. Selected composition only; see source for all limits.
Specification notes	Leaded brass: identify any lead-content restrictions in the RFQ.

Original technical reference | Jintian Copper

Mill composition table

jtcopper.com | External publisher; reference only

Selection reference, not a material certificate or guaranteed purchasing specification. Properties apply only to the stated grade, form, condition and test method. Branded examples do not establish Metalcorex stock or supplier identity. Confirm the production specification, supplier sheet and required records with your quotation.