COPPER & BRASS

T2

MATERIAL / REFERENCE CONDITION

Copper

Typical applications Electrical contacts and heat-transfer components

Material type	Copper
Condition / reference grade	Specify annealed, half-hard or hard condition
Manufacturing	Machining · forming
Reference data	Jintian publishes grade and temper-specific data. Strip data must not be used as bar-stock acceptance limits.
Specification notes	Specify conductivity, temper and joining requirements.

Original technical reference | Jintian Copper

Mill strip catalogue (PDF)

jtcopper.com | External publisher; reference only

Selection reference, not a material certificate or guaranteed purchasing specification. Properties apply only to the stated grade, form, condition and test method. Branded examples do not establish Metalcorex stock or supplier identity. Confirm the production specification, supplier sheet and required records with your quotation.