
KENWOOD

SERVICE BULLETIN

AMATEUR RADIO

SUBJECT
TM-211/411 AF GAIN CONTROL PART CHANGE
DATE
9-16-85

The original AF Gain control (R05-3424-15) has been replaced by a new part, with a new part number. The new part differs in mounting method and appearance. This should cause the operator no problems, and only requires a little change in the mounting method. The diagrams below are self explanitory:



Time required for this modification is 1 hour or less. @TKC985CLM