## **KENWOOD**

## SERVICE BULLETIN

## AMATEUR RADIO

SUBJECT		DATE
<u> </u>	TS-940S SIGNAL TO NOISE RATIO IMPROVEMENT	8-28-86

The following change will reduce the tendency of the Zener Diode in the Noise Blanker circuit to cause an increase in the ambient noise level. This change ensures that no current flows thru this diode in the normal receive position.


Parts required


560 ohm 1/4 watt resistor .....RD14CB2E561J

Procedure:

On the IF UNIT (X48-1430-00) change R23 from 330 ohms to 560 ohms.

This change will be incorporated in all models beginning with serial number 603xxxx.





foil Side

IF UNIT (X48-1430-00)

Time required for this modification is 1 hour or less. (C)82086TKCCLM