

SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

SUBJECT: TR-7600/7625 AUDIO TONE ON TX

DATE 8/10/79

Some TR-7600/7625 users report a ow background tone during TX, especially noticable at full quieting by the receiving station.

One the PLL unit X50-1580-00, change;

- ★ L18 from 22µH to 33µH ★ C61 from 22pF to 33pF
- * C60 from 22pF to 10pF
- ▶ C42 from 22pF to 39pF, or bridge 18pF across foil side & leave original C42 in place. No adjustment necessary.

New Part L18 33µH L40-3301-03 JEB/yn

