


 a) An enlarged section of hody and glaze shows that a crack has developed in the dry glaze layer.



 b) Głaze starts to melt and surface tension causes the glaze to pull away from the crack.



c) The body is left exposed. If the temperature is raised further the surface tension will be lower and the glaze might flow back and cover the body.