


A (x2)



B (x4)




C (Rx2/Lx2)




D (x4)



E (x4)



F (x2)



G (x1)

H (x1)


eh

ERKUL[®]
Products & Quality




FLYBAR V1

instructions




1




2



3



4



5

