

Re-inspection Report

Cedar Falls Fire Prevention Bureau

Report no. FM-26-0499 - Little Acorn Early Learning, Maple Street - re-inspection of FM-26-0425 - 09/02/2026

Items from report FM-26-0425

Item 1 - Kitchen fire extinguisher past its annual inspection tag: **Corrected. CLOSED.**

Item 2 - Exit sign over the rear door not illuminated: **Corrected. CLOSED.**

Item 3 - Extension cord used as permanent wiring in Toddler Room 2: **NOT CORRECTED - REPEAT VIOLATION.** Classification raised to Serious. Correct by 09/16/2026.

Item 5 - Fire alarm control panel showing a trouble signal: **Corrected. CLOSED.**

New violations

Item 1 - Fire door to the east hallway held open with a door wedge - Serious - correct within 7 days.

Item 4 of the original report was corrected on site and is not re-inspected.