# 1. Description


#### 1.1. Project

Project Name	planespotter-helloworld
Board Name	custom
Generated with:	STM32CubeMX 4.9.0
Date	10/02/2015

#### 1.2. MCU

MCU Series	STM32F0
MCU Line	STM32F0x0 Value Line
MCU name	STM32F030K6Tx
MCU Package	LQFP32
MCU Pin number	32

### 2. Pinout Configuration



## 3. Pins Configuration

Pin Number LQFP32	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
1	VDD	Power		
4	NRST	Reset		
5	VDDA	Power		
9	PA3	I/O	GPIO_EXTI3	
10	PA4 *	I/O	GPIO_Input	
16	VSS	Power		
17	VDD	Power		
19	PA9 **	I/O	USART1_TX	
20	PA10 **	I/O	USART1_RX	
28	PB5 *	I/O	GPIO_Output	
29	PB6 *	I/O	GPIO_Output	
30	PB7 *	I/O	GPIO_Output	
31	воото	Boot		
32	VSS	Power		

<sup>\*</sup> The pin is affected with an I/O function

<sup>\*\*</sup> The pin is affected with a peripheral function but no peripheral mode is activated

# 4. IPs and Middleware Configuration

Nothing is configured

\* User modified value

# 5. System Configuration

### 5.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
Single	PA9	USART1_TX	Alternate Function Push Pull	n/a	High *	
Mapped Signals	PA10	USART1_RX	Alternate Function Push Pull	n/a	High *	
GPIO	PA3	GPIO_EXTI3	External Interrupt	n/a	n/a	
			Mode with			
			Rising/Falling edge			
	PA4	GPIO_Input	Input mode	n/a	n/a	
	PB5	GPIO_Output	Output Push Pull	n/a	Low	
	PB6	GPIO_Output	Output Push Pull	n/a	Low	
	PB7	GPIO_Output	Output Push Pull	n/a	Low	

### 5.2. DMA configuration


nothing configured in DMA service

### 5.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority
System tick timer	true	0	0
Non maskable interrupt	unused		
RCC global interrupt	unused		
EXTI line 2 and 3 interrupts	unused		

<sup>\*</sup> User modified value

### 6. Clock Tree Configuration



### 7. Power Plugin report

#### 7.1. Microcontroller Selection

Series	STM32F0
Line	STM32F0x0 Value Line
MCU	STM32F030K6Tx
Datasheet	024849_Rev2

#### 7.2. Parameter Selection

Temperature	25
Vdd	3.6