

Ernst  
Alan  
F.H.

$S_1$	$S_0$	$a$	$b$	$X$	$n_1$	$n_0$
S <sub>0</sub>	0	0	0	0	0	0
	0	0	1	0	0	0
	0	1	0	0	0	1
	0	1	1	0	0	0
	1	0	0	0	0	0
S <sub>1</sub>	0	1	0	0	0	0
	0	1	1	0	0	0
	1	1	0	0	1	1
	1	1	1	0	1	0
S <sub>2</sub>	1	0	0	1	1	0
	1	0	1	1	1	1
	1	1	0	1	0	0
	1	1	1	1	1	0
S <sub>3</sub>	1	1	0	1	0	0
	1	1	1	1	1	1
	1	1	0	1	0	0
	1	1	1	1	1	1

$$X = S_1 S_0' + S_1 S_0$$

$S_1 S_0$	$ab$	00	01	11	10
00					
01					
11					
10					

$$X = S_1 S_0 a' b' + S_1 S_0' a' b + S_1 S_0' a b' + S_1 S_0' a b + S_1 S_0 a' b' + S_1 S_0 a' b + S_1 S_0 a b' + S_1 S_0 a b$$

$$n_1 = S_1' S_0 \cdot ab' + S_1' S_0 ab + S_1 S_0' a' b' + S_1 S_0' a' b + S_1 S_0 a' b + S_1 S_0 a b$$

$$n_0 = S_1' S_0' a b' + S_1' S_0 a b' + S_1 S_0' a' b + S_1 S_0 a' b + S_1 S_0 a b$$

$S_1 S_0$	$ab$	00	01	11	10
00					
01			1	1	
11			1	1	
10		1	1	1	

$$n_1 = S_1' S_0 a + S_1 b + S_1 S_0' a'$$

$S_1 S_0$	$ab$	00	01	11	10
00					
01					
11			1	1	
10		1			

$$n_0 = S_1' a b' + S_1 S_0 b + S_1 a' b$$

$$n_0 = S_1' a b' + S_1 b (S_0 + a')$$