USB_A : put Jumper _flash

Edit bloc **1190**

1190 edit

change **oldflash** to newflash (with the key 'a')

1190 load

the program erasing , burning , verify the data in flash and say **succes** !

After switch to USB_B , Open Jumper _flash , open Terminal on the COM (ex 9) , and type on 'espace' on the keyboard, an see eForth,