
2020-ME- 14-26


EE24BTECH11021 - Eshan Ray

- 14) Which of the following function f(z), of the complex variable z, is NOT analytic at all points on the complex plane?
 - a) $f(z) = z^2$
 - b) $f(z) = e^{z}$
 - c) $f(z) = \sin z$
 - d) $f(z) = \log z$
- 15) The members carrying zero force ($i \cdot e \cdot$ zero-force members) in the truss shown in the figure, for any load P > 0 with no appreciable deformation of the truss ($i \cdot e \cdot$ with no appreciable change in angles between the members), are




- a) BF and DH only
- b) BF, DH and GC only
- c) BF, DH, GC, CD and DE only
- d) BF, DH, GC, FG and GH only
- 16) A single-degree-of-freedom oscillator is subjected to harmonic excitation $F(t) = F_0 \cos(\omega t)$ as shown in the figure.

1



The non-zero value of ω , for which the amplitude of the force transmitted to the ground will be F_0 , is

- a) $\sqrt{\frac{k}{2m}}$
- b) $\sqrt{\frac{k}{m}}$
- c) $\sqrt{\frac{2k}{m}}$
- d) $2\sqrt{\frac{k}{m}}$
- 17) The stress state at a point in a material under plane stress condition is equi-biaxial tension with a magnitude of $10\,MPa$. If one unit on the $\sigma \tau$ plane is $1\,MPa$, the Mohr's circle representation of the state-of-stress is given by
 - a) a circle with a radius equal to principal stress and its center at the origin of the σ τ plane
 - b) a point on the σ axis at a distance of 10 units from the origin
 - c) a circle with a radius of 10 units on the σ τ plane
 - d) a point on the τ axis at a distance of 10 units from the origin
- 18) A four bar mechanism is shown below.



For the mechanism to be a crank-rocker mechanism, the length of the link PQ can be

a) 80 mm

- b) 200 mm
- c) 300 mm
- d) 350 mm
- 19) A helical gear with 20 pressure angle and 30 helix angle mounted at the mid-span of a shaft that is supported between two bearings at the ends. The nature of the stresses induced in the shaft is
 - a) normal stress due to bending only
 - b) normal stress due to bending in one plane and axial loading; shear stress due to torsion
 - c) normal stress due to bending in two planes and axial loading; shear stress due to torsion
 - d) normal stress due to bending in one plane; shear stress due to torsion
- 20) The crystal structure of γ ion (austenite phase) is
 - a) BCC
 - b) FCC
 - c) HCP
 - d) BCT
- 21) Match the following.

Heat treatment process	Effect
P: Tempering	1. Strengthening
Q: Quenching	2. Toughening
R: Annealing	3. Hardening
S: Normalizing	4. Softening

- a) P-2, Q-3, R-4, S-1
- b) P-1, Q-1, R-3, S-2
- c) P-3, Q-3, R-1, S-3
- d) P-4, Q-3, R-2, S-1
- 22) The base of a brass bracket needs rough grinding. For this purpose, the most suitable grinding wheel grade specification is
 - a) C30Q12V
 - b) A50G8V
 - c) C90J4B
 - d) A30D12V
- 23) In the critical Path Method (CPM), the cost-time slope of an activity is given by
 - a) Crash Cost Normal Cost Crash Time Normal Cost
 - b) Normal Cost
 Crash Time Normal Time
 Crash Cost
 - Crash Cost

 Crash Cost Normal Cost

 Crash Cost Normal Cost
 - d) Crash Cost Normal Cost
 Normal Time Crash Time
- 24) Froude number is the ratio of
 - a) buoyancy forces to viscous forces
 - b) inertia forces to viscous forces

- c) buoyancy forces to inertia forces
- d) inertia forces to gravity forces
- 25) Match the following non-dimensional numbers with the corresponding definitions :

Non-dimensional number	Definition
P: Reynolds number	1. Inertia force Viscous force
Q: Grashof number	2. Buoyancy force Viscous force
R: Nusselt number	3. Convective heat transfer Conduction heat transfer
S: Prandtl number	4. Momentum diffusivity Thermal diffusivity

a)
$$P-1, Q-3, R-2, S-4$$

b)
$$P-3, Q-1, R-2, S-4$$

c)
$$P-4, Q-3, R-1, S-2$$

d)
$$P-3, O-1, R-4, S-2$$

26) The velocity field of an incompressible flow in a Cartesian system is repressented by

$$\overrightarrow{V} = 2\left(x^2 - y^2\right)\hat{i} + v\hat{j} + 3\hat{k}$$

Which one of the following expressions for v is valid?

- a) -4xz + 6xy
- b) -4xy 4xz
- c) 4xz 6xy
- d) 4xy + 4xz