

Cut trace between Pin 2 on U30 between pad and 3.3V via. (in red)

Connect pin 2 to ground to TP8 ground pin as shown (in green)