BRIGHTWATER LABS

Workplace Safety Policy - Personal Protective Equipment (PPE)

Policy No. EHS-200 | Revision 3 | Effective January 6, 2026 | Owner: EHS Department
Fictional company - sample document for SafeSight demos.

1. Purpose

This policy defines the personal protective equipment required in each work area of the Brightwater Labs facility, the regulation each requirement is based on, and the potential penalty exposure associated with non-compliance.

2. Scope

Applies to all employees, contractors, and visitors entering the work areas listed in Section 4. Office areas and break rooms have no PPE requirements.

3. Enforcement and Penalty Exposure

Area supervisors are responsible for enforcing this policy. Where a dollar amount is listed in Section 4, it is the potential fine exposure the company has assessed for that requirement. Where no amount is listed, the current OSHA maximum penalty for the cited standard applies. Amounts describe potential exposure, not fines that have been assessed.

4. Zone Requirements

4.1 Chemistry Laboratory (Chem Lab)

Supervisor: chemlab.supervisor@brightwaterlabs.example

- Chemical-resistant nitrile gloves at all times when handling reagents. Ref: Sec. 4.1(a), 29 CFR 1910.138. Severity: Serious. Potential fine: $18,500 per violation.
- Half-face respirator or N95 mask when working with volatile solvents or powders. Ref: Sec. 4.1(b), 29 CFR 1910.134. Severity: Serious. Potential fine: $16,550.
- Indirect-vent chemical splash goggles. Ref: Sec. 4.1(c), 29 CFR 1910.133. Severity: Serious. Potential fine: $16,550.

4.2 Fabrication Shop

Supervisor: fab.supervisor@brightwaterlabs.example

- Hard hat (ANSI Z89.1 Type I) whenever overhead cranes are in operation. Ref: Sec. 4.2(a), 29 CFR 1910.135. Severity: Serious. Potential fine: $12,000 per violation.
- Cut-resistant gloves (ANSI A4 or higher) when handling sheet metal. Ref: Sec. 4.2(b), 29 CFR 1910.138. Severity: Serious.
- Safety glasses with side shields. Ref: Sec. 4.2(c), 29 CFR 1910.133.

4.3 Clean Room

Supervisor: cleanroom.lead@brightwaterlabs.example

- Surgical face mask covering nose and mouth. Ref: Sec. 4.3(a).
- Head cover (bouffant cap) with all hair contained. Ref: Sec. 4.3(b).
- Nitrile gloves, changed on every entry. Ref: Sec. 4.3(c), 29 CFR 1910.138. Potential fine: $9,500.

4.4 Loading Dock

Supervisor: dock.supervisor@brightwaterlabs.example

- Hard hat during all forklift and truck loading operations. Ref: Sec. 4.4(a), 29 CFR 1910.135. Severity: Serious.
- High-visibility safety vest (ANSI Class 2). Ref: Sec. 4.4(b). Severity: Other-than-serious. Potential fine: $4,000.
- Steel-toe safety boots. Ref: Sec. 4.4(c), 29 CFR 1910.136. Severity: Serious.

5. Reporting

Missing or damaged PPE must be reported to the area supervisor immediately. Replacement PPE is available at the stations at each zone entrance.

Approved by: J. Rivera, Director of Environment, Health & Safety | Next review: January 2027