

ADC_XPD_WAIT = 2, ADC_RSTB_WAIT = 1 (drawable stand-ins), CONTINUE_MODE_EN = 1, ADC_SAR1_PATT_TYPE = 0 (advance on done), triggered once

x axis is the ADC working clock; the waits count SAR conversions, T_{conv} compressed (24 clk real)

