

Nicolas GILLE (Valentinea)

- Is there some little holes to help breaking the holds ? I can't see them in the drl file :

---ICAPE: Yes, there are holes, they are shown in the 2rd drill layer, please check.

- Why do you use a 2rd file ? Is it a drl file ? If yes, why not putting them in the drl file ?

---ICAPE: we used the 2rd holes per our process requirement, we will do a second drilling process,

Yes, this is drill file, as there are twice drill process, so there are 1st and 2rd drill layer in our Gerber file,

- Why are those 4 holes not in the drl file ? :

---ICAPE: these 4 holes are within 2rd drill file.

- Can you generate the panel bottom paste please ? See attached the unitary board bottom paste.

---ICAPE: yes, please see attached update working gerber, please confirm if our working geber is ok?

- Can you make the pdf of the panelization same as 943D (see attached).

---ICAPE: ok, see attached panel drawing.