

Ambiflo DDS

LUMEN ASSET LCM - INVENTORY RECONCILIATION REPORT

Ambiflo Site No: A0001

CLLI code: CSRKCOCF

Site Name: Castlerock

Coordinates: 39.371693, -104.865836

Generated: 2026-02-23

1. NEW ITEMS FOUND IN BIM (Create in System of Record)

Total: 10

- [RACK] Name: NEW 23 x 15 x 84 Generic Rack
Building: 0001
Suite:
Line Up: 002
Bay: 004

- [RACK] Name: NEW 23 x 15 x 84 Generic Rack
Building: 0001
Suite:
Line Up: 004
Bay: 001

- [EQUIPMENT] Name: NEW Unidentified 1U Server
Building: 0002
Suite:
Line Up: 001
Bay: 001
U: 34

- [EQUIPMENT] Name: NEW Unidentified 1U Server
Building: 0002
Suite:
Line Up: 001
Bay: 001
U: 24

- [EQUIPMENT] Name: NEW Unidentified 1U Server
Building: 0002
Suite:
Line Up: 001
Bay: 001
U: 7

- [EQUIPMENT] Name: NEW Ciena 6500 MUX
Building: 0002
Suite:
Line Up: 001
Bay: 002
U: 6

- [EQUIPMENT] Name: NEW Unidentified 1U Server
Building: 0002
Suite:
Line Up: 001
Bay: 002
U: 27

- [EQUIPMENT] Name: NEW Unidentified 1U Server

Ambiflo DDS

Building: 0002
Suite:
Line Up: 001
Bay: 005
U: 13

- [EQUIPMENT] Name: NEW Ciena 6500 MUX
Building: 0003
Suite:
Line Up: 002
Bay: 008
U: 20

- [EQUIPMENT] Name: NEW Unidentified 4U
Building: 0003
Suite: 001
Line Up: 001
Bay: 010
U: 16

2. ATTRIBUTE MISMATCHES

Total: 9

- [undefined] (ID: 22077725)
 - > Line Up: BIM "002" → PRO "001"
 - > Bay No: BIM "003" → PRO "005"
- [undefined] (ID: 462348774)
 - > Line Up: BIM "003" → PRO "005"
- [undefined] (ID: 462348775)
 - > Line Up: BIM "003" → PRO "005"
- [undefined] (ID: 22077721)
 - > Line Up: BIM "004" → PRO "WMT"
 - > Bay No: BIM "002" → PRO "001"
- [undefined] (ID: 446535034)
 - > Line Up: BIM "001" → PRO "002"
- [undefined] (ID: 446648767)
 - > Bay No: BIM "002" → PRO "003"
- [undefined] (ID: 244224280)
 - > Line Up: BIM "001" → PRO "402"
 - > Bay No: BIM "003" → PRO "002"
- [undefined] (ID: 393074091)
 - > Line Up: BIM "001" → PRO "402"
 - > Bay No: BIM "004" → PRO "003"
- [undefined] (ID: 22462006)
 - > Line Up: BIM "001" → PRO "402"
 - > Bay No: BIM "005" → PRO "001"

3. MISSING IN BIM (Remove from System of Record)

Total: 17

- [RACK] ID: 21603449 | CSRKCOCF.001.0002..R01.001
Loc: CSRKCOCF.001.0002..R01.001
- [EQUIPMENT] ID: 21096143 | Generic OSP OCP Frame
Loc: CSRKCOCF.001.0001..001.001
- [EQUIPMENT] ID: 21096144 | Generic OSP OCP Frame
Loc: CSRKCOCF.001.0001..001.001
- [EQUIPMENT] ID: 20952415 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..001.002
- [EQUIPMENT] ID: 21587767 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..001.003

Ambiflo DDS

- [EQUIPMENT] ID: 20952416 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..001.003
- [EQUIPMENT] ID: 20952418 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..001.004
- [EQUIPMENT] ID: 20952417 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..001.005
- [EQUIPMENT] ID: 436253417 | CIENA 6500
Loc: CSRKCOCF.001.0001..002.002
- [EQUIPMENT] ID: 462348663 | Generic Optical Splitter (OSPOX)
Loc: CSRKCOCF.001.0001..005.001
- [EQUIPMENT] ID: 462348662 | Generic Optical Splitter (OSPOX)
Loc: CSRKCOCF.001.0001..005.001
- [EQUIPMENT] ID: 462348665 | Generic Optical Splitter (OSPOX)
Loc: CSRKCOCF.001.0001..005.002
- [EQUIPMENT] ID: 462348664 | Generic Optical Splitter (OSPOX)
Loc: CSRKCOCF.001.0001..005.002
- [EQUIPMENT] ID: 21296776 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..WMT.001
- [EQUIPMENT] ID: 21296780 | Generic Fiber Dist Panel
Loc: CSRKCOCF.001.0001..WMT.001
- [EQUIPMENT] ID: 8300393 | Unknown Unidentified Device
Loc: CSRKCOCF.001.0002..R01.001
- [EQUIPMENT] ID: 8282680 | Unknown Unidentified Device
Loc: CSRKCOCF.001.0002..R01.001