## 1. Issues when merging the codes

- Coordinate transformations: They are not invertible. Passing from Simulation to Controller carries lost of information.
- Trajectories definition:

I use a function  $x_c^*(t)$  and transform to  $x_s$  when needed