Control computer Reference signal Shaking Acceleration of Control Signal table, a(t)table Transfer function of

shaking table, TRF $G_e(s) = a(t)/r(t)$