
A4 — operator stopped
B4 — gate transitions: 38
Measured F_z^B (N)
Measured base Z (mm)
Time from execution start (s)
Time from execution start (s)