


Bug detected: RX,TX,RTS and CTS need to be swaped. New version of PCB needed.

Bug Fixed at 2025-07-22



Alinhamento.

AH1



Furo de Alinhamento

AH2



Furo de Alinhamento

Variante (se aplicável): [No Variations]			
Title			Organization
Size: A4			Country
Number: 1			My Address
Revision: V.1.2			My State
Date: 2025-11-18			My Zip Code
Time: 20:16:37			
Sheet1 of 1			
File: DONGLE02.SchDoc			

