


Bug detected: RX,TX,RTS and CTS need to be swaped. New version of PCB needed.

Bug Fixed at 2025-07-22



F1

Alinhamento.

AH1

Furo de Alinhamento

AH2

Furo de Alinhamento

Variante (se aplicável): **[No Variations]**

Title

Size: A4

Number:1

Revision:V.1.2

Date: 2026-06-22

Time: 21:57:00

Sheet1 of 1

File: DONGLE02.SchDoc

Organization
Country
My Address
My State
MyZipCode

Altium