

EV Diagnostic Report

VIN:

Code: P0A80

Description: Drive Battery Pack Deterioration

Severity: High

Battery Health: 25%

Diagnosis: Critical fault detected. Immediate inspection required.

Likely Causes:

- Battery cell degradation
- Excessive charge cycles
- Thermal damage

Recommended Actions:

- Replace degraded battery modules
- Run full battery diagnostic
- Inspect cell voltage balance
- Check thermal management system