

EV Diagnostic Report

Code: P0A80

Description: Replace Hybrid Battery Pack

Severity: High

Battery Health: 28%

Diagnosis: Serious issue. Immediate inspection required.