# Modelo lineal general: Bonding Strength vs. Curing Lights; Resin Types

#### Método

Codificación de factores (-1; 0; +1)

# Información del factor

Factor	Tipo	Niveles Valores
Curing Lights	Fijo	2 1; 2
Resin Types	Fijo	3 1; 2; 3

#### Análisis de Varianza

Fuente	GL	SC Ajust.	MC Ajust.	Valor F	Valor p
Curing Lights	1	54,67	54,67	2,59	0,120
Resin Types	2	76,45	38,22	1,81	0,184
Error	26	549,77	21,14		
Falta de ajuste	2	43,72	21,86	1,04	0,370
Error puro	24	506,05	21,09		
Total	29	680,89			

#### Resumen del modelo

		R-cuad.	R-cuad.
S	R-cuad.	(ajustado)	(pred)
4,59835	19,26%	9,94%	0,00%

# Coeficientes

	EE del			
Coef	coef.	Valor T	Valor p	FIV
18,703	0,840	22,28	0,000	
-1,350	0,840	-1,61	0,120	1,00
-1,94	1,19	-1,64	0,114	1,33
-0,02	1,19	-0,02	0,984	1,33
	18,703 -1,350 -1,94	Coef coef.   18,703 0,840   -1,350 0,840   -1,94 1,19	Coef coef. Valor T   18,703 0,840 22,28   -1,350 0,840 -1,61   -1,94 1,19 -1,64	Coef coef. Valor T Valor p   18,703 0,840 22,28 0,000   -1,350 0,840 -1,61 0,120   -1,94 1,19 -1,64 0,114

# Ecuación de regresión

Bonding Strength = 18,703 - 1,350 Curing Lights\_1 + 1,350 Curing Lights\_2 - 1,94 Resin Types\_1 - 0,02 Resin Types\_2 + 1,97 Resin Types\_3

# Ajustes y diagnósticos para observaciones poco comunes

Bonding			Resid		
Obs	Strength	Ajuste	Resid	est.	
16	27.10	18.11	8.99	2.10 R	

Residuo grande R

