

REFERENCE DRAWINGS		
DESCRIPTION DRAWINGS	NUMBER DRAWINGS	
P.& I. DIAGRAM - SPRAY DRYING - SECTION 64	2F11-10-105 Sh.1	
EXPANSION JOINTS SPECIFICATION	2F11-65-114	
VARIABLE SPRING HANGER SPECIFICATION	2F11-65-116	

PLUG VALVE 7 1300 PLUG VALVE 7 1300 PLUG VALVE 7 1300

TYP. DETAIL FOR PRESSURE TAPS

<u>LEGEND</u>

GUIDE

SUPPORT

SPRING HANGER

MULTI-LAYER TEXTILE EXPANSION JOINT

0	ISSUED FOR STRESS ANALYSIS	M.B.	16/04/12
REVISION Revisione	REVISION HISTORY Storia delle revisioni	DRAWN Autore	DATE Data
	f this document is stored as a digital file in a database. Approval process is digitally managed and no s te documento risiede in un database digitale.Il processo di approvazione è gestito via software e le firi		
	Desmet Ballestra S.p.A.	DRAWING Nr. / Disegno Nr. 2F11-60-104	
desmet ballestra	MILANO - Italy	CUSTOMER Nr. / Nr.	Cliente
	1	-	
JOB Commessa	2F11	SHEET Foglio	1
	2F11 SABIZ		1 0
Commessa PLANT		Foglio SHEET REVISION	0 -
Commessa PLANT Impianto TITLE	SABIZ	Foglio SHEET REVISION Revisione Foglio SCALE	1 0 - 64