




RMS: Cold vs Warm Start



Warm-Start Improvement Factor

 β_x at Undulator

Stage 11 Quad Current Continuity

