

This sheet is the reading copy — pin it up. The signing copy is **Form JC-01, the Job Card**, one per job, carrying these same sixteen stages with a date and a signature line against each.

COMMERCIAL

STAGES 1–5

1	LEAD	MOVED BY	Salesperson
2	ADVANCE PAID	MOVED BY	Selam
3	FINAL MEASUREMENT	MOVED BY	Designer
4	MATERIAL SELECTION	MOVED BY	Designer
5	PURCHASE APPROVAL	MOVED BY	Ephrata

FINANCE & PROCUREMENT

STAGES 6–9

6	MATERIALS ORDERED	MOVED BY	Getachew
7	MATERIALS RECEIVED	MOVED BY	Yordanos
8	FINAL PAYMENT REQUESTED	MOVED BY	Selam
9	FINAL PAYMENT RECEIVED	MOVED BY	Selam

PRODUCTION

STAGES 10–12

10	PRODUCTION APPROVED	MOVED BY	Liu
11	PRODUCTION COMPLETED	MOVED BY	Amha
12	QC RELEASED	MOVED BY	Wede

DELIVERY & AFTER-SALES

STAGES 13–16

13	READY FOR DELIVERY	MOVED BY	Selam
14	DELIVERED / INSTALLED	MOVED BY	Elias
15	CUSTOMER ACCEPTANCE	MOVED BY	Elias
16	AFTER-SALES FOLLOW-UP	MOVED BY	Salesperson

HOLD

NOT A STAGE — THE JOB KEEPS ITS NUMBER

—	HOLD / BLOCKED	SET BY	Ephrata only
---	----------------	--------	--------------

HARD STOPS — NON-NEGOTIABLE

- No production starts without 100% final payment confirmed by Selam and logged in the Job File.
- No delivery without QC release signed by Wede.
- No assembler payment without the physical Customer Acceptance Form in the Job File.