Reserve field report

Inventory

Seventeen seals were counted.

Six valves passed inspection.

Two bolts need replacement.

Constraints

Counts exclude the south shed.

Repeat the count on Monday.