

Report 1 arm

6/27/2026

Report overview

This report overview goes out to mention what we have done so far such as cadding it assembling it and reproton typing it. Currently I am having an issue with the 16 channel Servo motor driver. So in the future I will be installing another channel driver and then later adding a joystick for it.



Why?

This was done to hopefully fix the issues on facing this report that has gone over some of the cad work. I've done the assemblies and started Mark 2. Hopefully after that we can move on to writing a research paper on the inverse loads on hobby arms.

future

I will have to redevelop this by switching out the channel and adding a new channel driver. soon after that I can maybe make the adjustments necessary and then add joysticks.