

STEP 3




If it's not already assembled, attach the bracket with two hooks to the LCD mount plate as shown.




Mounted LCD shown here.



Cut a small notch out of the edge of one panel to allow the LCD cables to pass through to back. Make sure notch is larger enough to clear the channel bar, and that it's location will be hidden behind the mounted LCD screen.



Mount LCD to channel bar by sliding the hooks of the bracket into the slots on the channel bar as shown here and below.



Description		Date	Scale Engineer	
op-up Monitor Assembly			n/a	
Part #	Product Line	Revision		
PL-MOUNT				
3	2		1	_

8 7 6 5 4