PART: PL-MOUNT

STEP 1



If it's not already assembled, attach the bracket with two hooks to the LCD mount plate as shown

STEP 2



Cut a small notch out of the edge of one panel to allow the LCD cables to pass through to back. Make sure notch is larger enough to clear the channel bar, and that it's location will be hidden behind the mounted LCD screen.

STEP 3

Mount LCD to channel bar by sliding the hooks of the bracket into the slots on the channel bar as shown here and below

Mounted LCD shown here



Bracket Assembly

NT

MOD