



State Farm
P.O. Box 106169
Atlanta, GA 30348-6169
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

Structural Damage Claim Policy

This estimate is priced based on estimated market pricing for the cost of materials, labor, and other factors at the time of the loss.

Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, please contact us. If your contractor's estimate is higher than ours, you should contact us prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy terms, conditions and limits.

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you - not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.



Building Estimate Summary Guide

This summary guide is based on a sample estimate and is provided for reference only.

Please refer to the estimate for specifics of your claim.

State Farm Insurance

Insured: Smith, Joe & Jane	Estimate: 00-0000-000
Property: 1 Main Street	Claim number: 00-0000-000
Anywhere, IL 00000-0000	Policy Number: 00-00-0000-0
Type of Loss: Other	Price List: ILBL8F_MAR 13
Deductible: \$1,000.00	Restoration/Service/ Remodel
	F = Factored In, D = Do Not Apply

Summary for Dwelling

Line Item Total [1]		5,953.10
Material Sales Tax	@ 10.000% x 1,520.00	
Subtotal		6,105.10
General Contractor Overhead [2]	@ 10.0% x 6,105.10	610.51
General Contractor Profit	@ 10.0% x 6,105.10	
Replacement Cost Value (Including General Contractor Overhead and Profit [3])		7,326.12
Less Depreciation (Including Taxes) [4]		(832.50)
Less General Contractor Overhead & Profit on Recoverable & Non - recoverable Depreciation		(166.50)
Less Deductible [5]		
Net Actual Cash Value Payment [6]		

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes) [4]	832.50	
Less Non - recoverable Depreciation (Including Taxes) [7]		
Subtotal		312.50
General Contractor O&P on Depreciation	166.50	
Less General Contractor O&P on Non - recoverable Depreciation		
Subtotal		
Total Maximum Additional Amounts Available If Incurred [8]		
Total Amount of Claim If Incurred [9]		

Claim Representative

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

- 1. Line Item Total** – Total value of all line items in the estimate plus possible adjustments for *labor minimums*. *Labor Minimum* is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
- 2. General Contractor's Overhead and Profit** – General contractor's charge for coordinating your repairs.
- 3. Replacement Cost Value (RCV)** – Estimated cost to repair or replace damaged property.
- 4. Depreciation** – The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
- 5. Deductible** – The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
- 6. Net Actual Cash Value Payment (ACV)** – The repair or replacement cost of the damaged part of the property less *depreciation* and *deductible*.
- 7. Non Recoverable Depreciation** – *Depreciation* applied to items that are not eligible for replacement cost benefits.
- 8. Total Maximum Additional Amount if Incurred** – Total amount of recoverable depreciation after actual repair or replacement of the property.
- 9. Total Amount of Claim if Incurred** – Total amount of the claim, including *net actual cash value payment* and *total maximum additional amount available if incurred*.

State Farm

CAROLIN, TERRY

35-43Q9-85G

Insured: CAROLIN, TERRY
Property: 8175 OXFORD DR
STRONGSVILLE, OH 44149-1516

Estimate: 35-43Q9-85G
Claim Number: 3543Q985G
Policy Number: 703646318
Price List: OHCL28_DEC22
Restoration/Service/Remodel

Home: 440-243-6458
Cellular: 440-243-6458
Type of Loss: Wind Damage
Deductible: \$1,329.00
Date of Loss: 12/23/2022
Date Inspected: 1/17/2023

**Summary for Exterior - Coverage A - Dwelling - 35 Windstorm
and Hail**

Line Item Total	9,245.33
Material Sales Tax	290.95
Replacement Cost Value	9,536.28
Less Depreciation (Including Taxes)	(897.37)
Less Deductible	(1,329.00)
Net Actual Cash Value Payment	\$7,309.91

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes)	897.37
Replacement Cost Benefits	897.37
Total Maximum Additional Amount Available If Incurred	897.37
Total Amount of Claim If Incurred	\$8,207.28

Orndorff, Terra
844-458-4300

**ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND
LIMITS OF YOUR POLICY.**



Explanation of Building Replacement Cost Benefits
Homeowner Policy
Exterior - Coverage A - Dwelling - 35 Windstorm and Hail

To: Name: CAROLIN, TERRY
Address: 8175 OXFORD DR
City: STRONGSVILLE
State/Zip: OH, 44149-1516

Insured: CAROLIN, TERRY
Date of Loss: 12/23/2022

Claim Number: 3543Q985G
Cause of Loss: WIND

Your insurance policy provides replacement cost benefits for some or all of the loss or damage to your dwelling or structures. Replacement cost benefits pays the actual and necessary cost of repair or replacement, without a deduction for depreciation, subject to your policy's limit of liability. To receive replacement cost benefits you must:

1. Complete the actual repair or replacement of the damaged part of the property within two years of the date of loss;
2. Promptly notify us within 30 days after the work has been completed; and
3. Confirm completion of repair or replacement, by submitting invoices, receipts or other documentation to your agent or claim office.

Until these requirements have been satisfied, our payment(s) to you will be for the actual cash value of the damaged part of the property, which may include a deduction for depreciation.

Without waiving the above requirements, we will consider paying replacement cost benefits prior to actual repair or replacement if we determine repair or replacement costs will be incurred because repairs are substantially under way or you present a signed contract acceptable to us.

The estimate to repair or replace your damaged property is \$9,536.28 . The enclosed claim payment to you of \$7,309.91 is for the actual cash value of the damaged property at the time of loss, less any deductible that may apply. We determined the actual cash value by deducting depreciation from the estimated repair or replacement cost. Our estimate details the depreciation applied to your loss. Based on our estimate, the additional amount available to you for replacement cost benefits (recoverable depreciation) is \$ 897.37 .

If you cannot have the repairs completed for the repair/replacement cost estimated, please contact your claim specialist prior to beginning repairs.

All policy provisions apply to your claim.

State Farm

CAROLIN, TERRY

35-43Q9-85G

Source - EagleView Roof & Walls

Exterior




Ext_Surfaces

39.10 SF Walls
39.10 SF Walls & Ceiling

6.41 LF Floor Perimeter

Window	1' X 4' 6"	Opens into Exterior
Window	1' X 4' 6"	Opens into Exterior
Window	1' X 4' 6"	Opens into Exterior
Window	1' X 4' 6"	Opens into Exterior

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* 1. Roofing (Bid Item) - ITEL						
1.00 EA	181.59 *N	5.96	187.55			187.55
CO authorized ITEL testing by CTR on 02/27/2023. Allowing line item for testing fee of \$181.59 but not service call of \$245.00 for retrieval of sample.						
2. Dumpster load - Approx. 12 yards, 1-3 tons of debris						
1.00 EA	375.00 N	0.00	375.00			375.00
Totals: Ext_Surfaces		5.96	562.55		0.00	562.55



House Roof

2,246.96 Surface Area
370.42 Total Perimeter Length


22.47 Number of Squares
61.00 Total Ridge Length

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
No storm related damage to the roof.						
Totals: House Roof		0.00	0.00		0.00	0.00

State Farm

CAROLIN, TERRY

35-43Q9-85G



Right

473.04 SF Walls
473.04 SF Walls & Ceiling

57.03 LF Floor Perimeter

Window 3' X 3' Opens into Exterior
Window 5' 6" X 2' Opens into Exterior

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* 3. Right Elevation per The Third Estimate						
1.00 EA	2,847.40 *N	93.39	2,940.79		(294.08)	2,646.71
				Avg.	10.00%	
4. R&R Siding - vinyl	459.86 SF					PER BID
5. R&R Attic vent - gable end - vinyl	1.00 EA					PER BID
6. Detach & Reset Shutters - simulated wood (polystyrene)	1.00 EA					PER BID
7. R&R Rigid foam insulation board - 1/2"	449.08 SF					PER BID
Totals: Right		93.39	2,940.79		294.08	2,646.71

Back



760.23 SF Walls
760.23 SF Walls & Ceiling

94.59 LF Floor Perimeter

Window 3' X 4' Opens into Exterior
Window 4' 7 13/16" X 4' Opens into Exterior
Window 5' X 4' 6" Opens into Exterior
Door 3' X 6' 11 1/2" Opens into Exterior
Window 3' X 7' Opens into Exterior
Window 5' 6" X 4' 6" Opens into Exterior
Window 5' 2 7/8" X 5' 11 11/16" Opens into Exterior

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
----------	------------	-----	-----	-----------------------	------------------	-----


State Farm

CAROLIN, TERRY

35-43Q9-85G

CONTINUED - Back

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* 8. Back Elevation per The Third Estimate bid						
1.00 EA	5,841.34 *N	191.60	6,032.94	Avg.	(603.29) 10.00%	5,429.65
9. R&R Siding - vinyl						
732.29 SF						PER BID
10. Detach & Reset Gutter / downspout - aluminum - 6"						
36.00 LF						PER BID
11. Detach & Reset Exterior light fixture						
1.00 EA						PER BID
12. R&R Disconnect box - 30 amp - non fused						
1.00 EA						PER BID
13. R&R Attic vent - gable end - vinyl						
1.00 EA						PER BID
14. Detach & Reset Exterior faucet / hose bibb						
1.00 EA						PER BID
15. R&R Rigid foam insulation board - 1/2"						
722.92 SF						PER BID
Totals: Back		191.60	6,032.94		603.29	5,429.65



Left

430.43 SF Walls
430.43 SF Walls & Ceiling

57.03 LF Floor Perimeter

Window

2' X 2'

Opens into Exterior

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* 16. Left Elevation per The Third Estimate bid						
1.00 EA						PWARR
17. R&R Siding - vinyl						
421.36 SF						PER BID
18. R&R Fanfold foam insulation board - 1/4"						
421.36 SF						PER BID
19. R&R Meter base and main disconnect - 200 amp						
1.00 EA						PER BID


State Farm

CAROLIN, TERRY

35-43Q9-85G

CONTINUED - Left

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
20. R&R Trunk cable - aluminum - 4 wire 2/0	8.00 LF					PER BID
21. R&R Rigid conduit, 2"	8.00 LF					PER BID
22. R&R Meter mast for overhead power - 2" conduit	1.00 EA					PER BID
23. Low voltage box - Detach & reset	1.00 EA					PER BID
24. Detach & Reset Exterior faucet / hose bibb	1.00 EA					PER BID
Totals: Left		0.00	0.00		0.00	0.00



Front

559.68 SF Walls
559.68 SF Walls & Ceiling

99.02 LF Floor Perimeter

Window	3' X 7'	Opens into Exterior
Door	15' 6" X 7' 1/2"	Opens into Exterior
Window	6' X 4' 4 9/16"	Opens into Exterior
Window	2' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	1' X 4' 6"	Opens into Exterior

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* 25. Front Elevation per The Third Estimate bid	1.00 EA					PWARR
26. R&R Siding - vinyl	544.86 SF					PER BID
27. R&R Fanfold foam insulation board - 1/4"	544.86 SF					PER BID
28. Detach & Reset Shutters - simulated wood (polystyrene)	4.00 EA					PER BID

State Farm

CAROLIN, TERRY

35-43Q9-85G

CONTINUED - Front


QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
29. R&R Attic vent - gable end - vinyl						
1.00 EA						PER BID
30. Detach & Reset Gutter / downspout - aluminum - 6"						
12.00 LF						PER BID
31. Detach & Reset Exterior light fixture						
1.00 EA						PER BID
Totals: Front		0.00	0.00		0.00	0.00
Area Totals: Exterior						
2,262.48 SF Walls		314.09 Exterior Perimeter		2,262.48 SF Walls and Ceiling		
2,262.48 Exterior Wall Area		of Walls		314.09 LF Floor Perimeter		
2,246.96 Surface Area		22.47 Number of Squares		370.42 Total Perimeter Length		
61.00 Total Ridge Length						
Total: Exterior		290.95	9,536.28		897.37	8,638.91
Area Totals: Source - EagleView Roof & Walls						
2,262.48 SF Walls		314.09 Exterior Perimeter		2,262.48 SF Walls and Ceiling		
2,262.48 Exterior Wall Area		of Walls		314.09 LF Floor Perimeter		
2,246.96 Surface Area		22.47 Number of Squares		370.42 Total Perimeter Length		
61.00 Total Ridge Length						
Total: Source - EagleView Roof & Walls		290.95	9,536.28		897.37	8,638.91
Line Item Totals: 35-43Q9-85G		290.95	9,536.28		897.37	8,638.91

Grand Total Areas:

2,262.48 SF Walls		2,262.48 SF Walls and Ceiling	
		314.09 LF Floor Perimeter	
2,262.48 Exterior Wall Area	314.09 Exterior Perimeter of Walls		
2,246.96 Surface Area	22.47 Number of Squares	370.42 Total Perimeter Length	
61.00 Total Ridge Length			

Recap of Taxes, Overhead and Profit

	GC Overhead (0%)	GC Profit (0%)	Material Tax (0%)	Material Sales Tax (8%)	Cln Matl Tax (8%)	Cln&Carpet Svc Tax (8%)
Line Items	0.00	0.00	0.00	290.95	0.00	0.00
Total	0.00	0.00	0.00	290.95	0.00	0.00



Exterior