

**Alacrity Solutions**  
**A USAA Service Provider**  
**PO BOX 33490**  
**San Antonio, TX 78265**  
**800-531-8722**  
**9/15/2025**

Insured: First Lieutenant James Tangenberg  
Property: 3851 Shawnee St Nw  
Uniontown, OH 44685-9133  
Home: 3851 Shawnee St Nw  
Uniontown, OH 44685-9133

Home: (330) 699-5896  
E-mail: jimtangenberg@yahoo.com

Claim Rep.: Robert White  
Business: 9725 Windermere Blvd,  
Fishers, IN 46037

Business: (330) 592-7763  
Loss Email Address: 3j7z9hpd5jbkw@claims.usaa.com

Estimator: Robert White  
Business: 9725 Windermere Blvd,  
Fishers, IN 46037

Business: (330) 592-7763  
Loss Email Address: 3j7z9hpd5jbkw@claims.usaa.com

**Member Number:** 001226852

**Policy Number:** 001226852-91A

**L/R Number:** 802

**Type of Loss:** WTR-ROF

**Cause of Loss:** Other

**Insurance Company:** UNITED SERVICES AUTOMOBILE ASSOCIATION

| Coverage                | Deductible | Policy Limit |
|-------------------------|------------|--------------|
| Dwelling                | \$3,930.00 | \$393,000.00 |
| Dwelling - Code Upgrade | \$0.00     | \$0.00       |

Date Contacted: 9/12/2025 1:15 PM

Date of Loss: 5/1/2025 12:00 AM

Date Inspected: 9/15/2025 11:30 AM

Date Est. Completed: 9/15/2025 3:54 PM

Date Received: 9/12/2025 9:42 AM

Date Entered: 9/12/2025 1:08 PM

Price List: OHCA8X\_SEP25  
Restoration/Service/Remodel

**Summary for Dwelling**

|                               |                    |
|-------------------------------|--------------------|
| Line Item Total               | 10,438.30          |
| Material Sales Tax            | 238.57             |
| <b>Replacement Cost Value</b> | <b>\$10,676.87</b> |
| Less Deductible               | (3,930.00)         |
| <b>Net Claim</b>              | <b>\$6,746.87</b>  |

Robert White

## Alacrity Solutions

First Lieutenant James Tangenberg

9/15/2025

Page: 2

Insured: First Lieutenant James Tangenberg  
Property: 3851 Shawnee St Nw  
Uniontown, OH 44685-9133  
Home: 3851 Shawnee St Nw  
Uniontown, OH 44685-9133

Home: (330) 699-5896  
E-mail: jimtangenberg@yahoo.com

Claim Rep.: Robert White  
Business: 9725 Windermere Blvd,  
Fishers, IN 46037

Business: (330) 592-7763  
Loss Email Address: 3j7z9hpd5jbkw@claims.usaa.com

Estimator: Robert White  
Business: 9725 Windermere Blvd,  
Fishers, IN 46037

Business: (330) 592-7763  
Loss Email Address: 3j7z9hpd5jbkw@claims.usaa.com

**Member Number:** 001226852

**Policy Number:** 001226852-91A

**L/R Number:** 802

**Type of Loss:** WTR-ROF

**Cause of Loss:** Other

**Insurance Company:** UNITED SERVICES AUTOMOBILE ASSOCIATION

| Coverage                | Deductible | Policy Limit |
|-------------------------|------------|--------------|
| Dwelling                | \$3,930.00 | \$393,000.00 |
| Dwelling - Code Upgrade | \$0.00     | \$0.00       |

Date Contacted: 9/12/2025 1:15 PM  
Date of Loss: 5/1/2025 12:00 AM  
Date Inspected: 9/15/2025 11:30 AM  
Date Est. Completed: 9/15/2025 3:54 PM

Date Received: 9/12/2025 9:42 AM  
Date Entered: 9/12/2025 1:08 PM

Price List: OHCA8X\_SEP25  
Restoration/Service/Remodel

### Summary for Dwelling - Code Upgrade

|                               |               |
|-------------------------------|---------------|
| Line Item Total               | 0.00          |
| <b>Replacement Cost Value</b> | <b>\$0.00</b> |
| <b>Net Claim</b>              | <b>\$0.00</b> |

### Dwelling - Code Upgrade Paid When Incurred

|                                                      |                 |
|------------------------------------------------------|-----------------|
| Line Item Total                                      | 943.39          |
| Material Sales Tax                                   | 18.55           |
| <b>Replacement Cost Value</b>                        | <b>\$961.94</b> |
| <b>Total Paid When Incurred</b>                      | <b>\$961.94</b> |
| <b>Net Claim</b>                                     | <b>\$0.00</b>   |
| <b>Net Claim if Additional Amounts are Recovered</b> | <b>\$961.94</b> |

---


Robert White

"ANY PERSON WHO, WITH INTENT TO DEFRAUD OR KNOWING THAT HE IS FACILITATING A FRAUD AGAINST AN INSURER, SUBMITS AN APPLICATION OR FILES A CLAIM CONTAINING A FALSE OR DECEPTIVE STATEMENT IS GUILTY OF INSURANCE FRAUD." OH CODE §3999.21

Please contact our adjuster if you believe a supplement to this estimate is needed. Before we will consider a supplement to this estimate, we must have the opportunity to re-inspect the damages prior to the supplemental work being done.

Recap of Taxes

|            | Material Tax (0%) | Material Sales Tax (6.5%) | Cln Matl Tax (6.5%) | Cln&Carpet Svc Tax (6.5%) |
|------------|-------------------|---------------------------|---------------------|---------------------------|
| Line Items | 0.00              | 238.57                    | 0.00                | 0.00                      |
| Total      | 0.00              | 238.57                    | 0.00                | 0.00                      |

**FIRST\_LIEUTENANT\_JA1****Main Level****Dwelling roof**

2597.42 Surface Area  
222.76 Total Perimeter Length

25.97 Number of Squares  
83.37 Total Ridge Length

| QUANTITY                                                                                                                                                                          | UNIT   | TAX           | O&P         | RCV              | AGE/LIFE | DEPREC.     | ACV              |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------------|-------------|------------------|----------|-------------|------------------|
| 1. Tear off, haul and dispose of comp. shingles - 3 tab                                                                                                                           |        |               |             |                  |          |             |                  |
| 25.97 SQ                                                                                                                                                                          | 68.06  | 0.00          | 0.00        | 1,767.52         | 0/25 yrs | (0.00)      | 1,767.52         |
| 2. Ice & water barrier                                                                                                                                                            |        |               |             |                  |          |             |                  |
| 582.34 SF                                                                                                                                                                         | 1.62   | 18.55         | 0.00        | 961.94           | 0/30 yrs | (0.00)      | 961.94           |
| This item did not previously exist or expands the scope of repairs, but is required by current building codes. The code upgrade cost is payable when incurred, subject to limits. |        |               |             |                  |          |             |                  |
| 3. Roofing felt - 15 lb.                                                                                                                                                          |        |               |             |                  |          |             |                  |
| 20.15 SQ                                                                                                                                                                          | 33.85  | 11.05         | 0.00        | 693.13           | 0/20 yrs | (0.00)      | 693.13           |
| 4. Drip edge                                                                                                                                                                      |        |               |             |                  |          |             |                  |
| 222.76 LF                                                                                                                                                                         | 2.70   | 15.93         | 0.00        | 617.38           | 0/35 yrs | (0.00)      | 617.38           |
| 5. Flashing - pipe jack - lead                                                                                                                                                    |        |               |             |                  |          |             |                  |
| 1.00 EA                                                                                                                                                                           | 85.13  | 3.46          | 0.00        | 88.59            | 0/35 yrs | (0.00)      | 88.59            |
| 6. Digital satellite system - Detach & reset                                                                                                                                      |        |               |             |                  |          |             |                  |
| 1.00 EA                                                                                                                                                                           | 42.59  | 0.00          | 0.00        | 42.59            | 0/NA     | (0.00)      | 42.59            |
| 7. Detach & Reset Roof vent - turtle type - Metal                                                                                                                                 |        |               |             |                  |          |             |                  |
| 3.00 EA                                                                                                                                                                           | 57.46  | 0.19          | 0.00        | 172.57           | 0/35 yrs | (0.00)      | 172.57           |
| 8. 3 tab - 25 yr. - comp. shingle roofing - w/out felt                                                                                                                            |        |               |             |                  |          |             |                  |
| 28.67 SQ                                                                                                                                                                          | 230.17 | 207.94        | 0.00        | 6,806.91         | 0/25 yrs | (0.00)      | 6,806.91         |
| Component RFG240 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 15 Sep 2025. See attached document for more details.                                     |        |               |             |                  |          |             |                  |
| 10% waste allows for ridge cap shingles included.                                                                                                                                 |        |               |             |                  |          |             |                  |
| <b>Totals: Dwelling roof</b>                                                                                                                                                      |        | <b>238.57</b> | <b>0.00</b> | <b>10,188.69</b> |          | <b>0.00</b> | <b>10,188.69</b> |

**Front Elevation**

| QUANTITY                                           | UNIT | TAX         | O&P         | RCV           | AGE/LIFE | DEPREC.     | ACV           |
|----------------------------------------------------|------|-------------|-------------|---------------|----------|-------------|---------------|
| 9. Detach & Reset Gutter aluminum - up to 5"*      |      |             |             |               |          |             |               |
| 20.00 LF                                           | 5.66 | 0.00        | 0.00        | 113.20        | 0/25 yrs | (0.00)      | 113.20        |
| allowance to reset pins to gutter detached by wind |      |             |             |               |          |             |               |
| <b>Totals: Front Elevation</b>                     |      | <b>0.00</b> | <b>0.00</b> | <b>113.20</b> |          | <b>0.00</b> | <b>113.20</b> |

# Alacrity Solutions

First Lieutenant James Tangenberg

9/15/2025

Page: 6

## Rear Elevation

| QUANTITY                                           | UNIT | TAX           | O&P         | RCV              | AGE/LIFE | DEPREC.     | ACV              |
|----------------------------------------------------|------|---------------|-------------|------------------|----------|-------------|------------------|
| 10. Detach & Reset Gutter aluminum - up to 5"*     |      |               |             |                  |          |             |                  |
| 66.25 LF                                           | 5.66 | 0.00          | 0.00        | 374.98           | 0/25 yrs | (0.00)      | 374.98           |
| allowance to reset pins to gutter detached by wind |      |               |             |                  |          |             |                  |
| <b>Totals: Rear Elevation</b>                      |      | <b>0.00</b>   | <b>0.00</b> | <b>374.98</b>    |          | <b>0.00</b> | <b>374.98</b>    |
| <b>Total: Main Level</b>                           |      | <b>238.57</b> | <b>0.00</b> | <b>10,676.87</b> |          | <b>0.00</b> | <b>10,676.87</b> |
| <b>Line Item Totals: FIRST_LIEUTENANT_JA1</b>      |      | <b>238.57</b> | <b>0.00</b> | <b>10,676.87</b> |          | <b>0.00</b> | <b>10,676.87</b> |

## Grand Total Areas:

|                           |                                  |                               |
|---------------------------|----------------------------------|-------------------------------|
| 0.00 SF Walls             | 0.00 SF Ceiling                  | 0.00 SF Walls and Ceiling     |
| 0.00 SF Floor             | 0.00 SY Flooring                 | 0.00 LF Floor Perimeter       |
| 0.00 SF Long Wall         | 0.00 SF Short Wall               | 0.00 LF Ceil. Perimeter       |
| 0.00 Floor Area           | 0.00 Total Area                  | 0.00 Interior Wall Area       |
| 479.45 Exterior Wall Area | 0.00 Exterior Perimeter of Walls |                               |
| 2,597.42 Surface Area     | 25.97 Number of Squares          | 222.76 Total Perimeter Length |
| 83.37 Total Ridge Length  | 0.00 Total Hip Length            |                               |

| Coverage                | Item Total | %       | ACV Total | %       |
|-------------------------|------------|---------|-----------|---------|
| Dwelling                | 10,438.30  | 100.00% | 10,676.87 | 100.00% |
| Dwelling - Code Upgrade | 0.00       | 0.00%   | 0.00      | 0.00%   |
| Total                   | 10,438.30  | 100.00% | 10,676.87 | 100.00% |

Recap by Room

Estimate: FIRST\_LIEUTENANT\_JA1

|                           |           |           |         |
|---------------------------|-----------|-----------|---------|
| Area: Main Level          |           |           |         |
| Dwelling roof             |           | 9,950.12  | 95.32%  |
| Coverage: Dwelling        | 100.00% = | 9,950.12  |         |
| Front Elevation           |           | 113.20    | 1.08%   |
| Coverage: Dwelling        | 100.00% = | 113.20    |         |
| Rear Elevation            |           | 374.98    | 3.59%   |
| Coverage: Dwelling        | 100.00% = | 374.98    |         |
| Area Subtotal: Main Level |           | 10,438.30 | 100.00% |
| Coverage: Dwelling        | 100.00% = | 10,438.30 |         |
| Subtotal of Areas         |           | 10,438.30 | 100.00% |
| Coverage: Dwelling        | 100.00% = | 10,438.30 |         |
| Total                     |           | 10,438.30 | 100.00% |

**Recap by Category**

| <b>Items</b>                        |   |           | <b>Total</b>     | <b>%</b>       |
|-------------------------------------|---|-----------|------------------|----------------|
| <b>ROOFING</b>                      |   |           | <b>9,950.12</b>  | <b>93.19%</b>  |
| Coverage: Dwelling                  | @ | 100.00% = | 9,950.12         |                |
| <b>SOFFIT, FASCIA, &amp; GUTTER</b> |   |           | <b>488.18</b>    | <b>4.57%</b>   |
| Coverage: Dwelling                  | @ | 100.00% = | 488.18           |                |
| <b>Subtotal</b>                     |   |           | <b>10,438.30</b> | <b>97.77%</b>  |
| <b>Material Sales Tax</b>           |   |           | <b>238.57</b>    | <b>2.23%</b>   |
| Coverage: Dwelling                  | @ | 100.00% = | 238.57           |                |
| <b>Total</b>                        |   |           | <b>10,676.87</b> | <b>100.00%</b> |

**FREQUENTLY ASKED QUESTIONS**

The FAQ's and answers below will be helpful in the claim process. If there is any conflict between these answers and the policy, your policy controls. Please read your policy.

**How is my initial Dwelling payment determined?**

Subject to the applicable deductible and policy conditions, Dwelling payments are generally based on the cost to repair or replace the damaged property with similar construction and for the same use on the same premises. When the cost to repair or replace the damaged dwelling exceeds \$5000, USAA will pay a portion of the claim up front (the actual cash value of the loss), and the balance (recoverable depreciation) when the repairs are complete.

**How do I collect the recoverable depreciation?**

Where initial payment for Dwelling loss is in the amount of Actual Cash Value, to receive additional amounts (recoverable depreciation), you must complete the actual repair or replacement of the damaged part of the property. When repair or replacement is actually completed, the policy will pay the covered additional amount you actually and necessarily incurred to repair or replace the property, but not to exceed the approved replacement cost of your claim (our cost). In no case will USAA pay more than the total amount of the actual repairs less your policy deductible.

**Why is the check made out to me and someone else (or some other company)?**

If your check includes the name of your mortgage company it is because we are required to include their name on our payment to you, per the mortgage clause on your policy. The check must be presented to them for their endorsement prior to submitting it to our bank for payment. Incomplete endorsements will result in the check being returned without payment. Please contact us if the mortgagee information is incorrect so that we may update that information and issue a correct payment to you.

**What if I'm not going to repair or replace my damaged property using the same material?**

Please contact us if you choose to repair or replace the damaged building part with a different material or type of construction from what is on our estimate. Replacement or repair differing from the original estimate could affect any replacement cost claim you are otherwise eligible to collect.

**What if my contractor's estimate is different from USAA's estimate?**

Show the USAA estimate to your contractor. If your contractor's estimate is higher, please contact USAA prior to starting the repairs to your home as the additional charges may not be covered.