### LCD Interfacing on Firebird V Robot

e-Yantra Team

Embedded Real-Time Systems (ERTS) Lab Indian Institute of Technology, Bombay





### Agenda for Discussion

- Introduction
  - LCD Definition
- Understanding LCD
  - Pin Configuration
  - Control Pins
  - Data Pins
- 3 LCD Programming
  - LCD Interfacing
  - Some Important commands
  - LCD Initialization
  - Programming









A liquid crystal display (LCD) is a thin, flat panel used for electronically displaying information such as text, images, and moving pictures





- ① A liquid crystal display (LCD) is a thin, flat panel used for electronically displaying information such as text, images, and moving pictures
- LCDs are economical and easy to use device. These are most commonly used display devices in an embedded system. Commonly available display are set up as 16 to 20 characters by 1 to 4 lines





- A liquid crystal display (LCD) is a thin, flat panel used for electronically displaying information such as text, images, and moving pictures
- LCDs are economical and easy to use device. These are most commonly used display devices in an embedded system. Commonly available display are set up as 16 to 20 characters by 1 to 4 lines





- A liquid crystal display (LCD) is a thin, flat panel used for electronically displaying information such as text, images, and moving pictures
- LCDs are economical and easy to use device. These are most commonly used display devices in an embedded system. Commonly available display are set up as 16 to 20 characters by 1 to 4 lines











## Dot Matrix Liquid Crystal Display





### Dot Matrix Liquid Crystal Display

■ LCD used here has HD44780 dot matrix lcd controller. It is also called 16x2 Alpha Numeric LCD





### Dot Matrix Liquid Crystal Display

- LCD used here has HD44780 dot matrix lcd controller. It is also called 16x2 Alpha Numeric LCD
- 2 It can be configured to drive a dot-matrix liquid crystal display








# Pin-Configuration






# Pin-Configuration







# Pin-Configuration



Pin	Description
Vss	Ground
Vdd	Supply Voltage
Vee	Contrast Voltage
Vdd,Vss	Back Light Supply
RS	Register Select
RW	Read/Write
Е	Enable
D0-D7	Bidirectional Data Bus











Register Select





- Register Select
  - If RS=0; Command Register





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- Read/Write Select





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- @ Read/Write Select
  - If RW=0; Write Mode





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- @ Read/Write Select
  - If RW=0; Write Mode
  - If RW=1; Read Mode





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- @ Read/Write Select
  - If RW=0; Write Mode
  - If RW=1; Read Mode
- 6 Enable





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- @ Read/Write Select
  - If RW=0; Write Mode
  - If RW=1; Read Mode
- Enable
  - Used to latch the data present on the data pins





- Register Select
  - If RS=0; Command Register
  - If RS=1; Data Register
- @ Read/Write Select
  - If RW=0; Write Mode
  - If RW=1; Read Mode
- Enable
  - Used to latch the data present on the data pins
  - A high-to-low edge is needed to latch the data











Data Lines





- O Data Lines
  - There are 8 data pins from D0 to D7





- O Data Lines
  - There are 8 data pins from D0 to D7
  - Bidirectional Data / Command Pins





- O Data Lines
  - There are 8 data pins from D0 to D7
  - Bidirectional Data / Command Pins
  - Alpha Numeric Character are sent in ASCII format





- Data Lines
  - There are 8 data pins from D0 to D7
  - Bidirectional Data / Command Pins
  - Alpha Numeric Character are sent in ASCII format
  - We can use LCD either 8 bit mode or 4 bit mode





- Opening Data Lines
  - There are 8 data pins from D0 to D7
  - Bidirectional Data / Command Pins
  - Alpha Numeric Character are sent in ASCII format
  - We can use LCD either 8 bit mode or 4 bit mode
  - We use 4 bit mode: only D4 to D7 data pins are used








LCD Interfacing
Some Important commands
LCD Initialization
Programming

# LCD Interfacing





# LCD Interfacing









Some Important commands LCD Initialization Programming

## Some Important Commands







LCD Interfacing
Some Important commands
LCD Initialization
Programming

## Some Important Commands

Description Hex





# Some Important Commands

ſ	Description		
ſ	Function set (8-bit interface, 2 lines, 5*7 Pixels)	38	





# Some Important Commands

Description		
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38	
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28	





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02
Display ON cursor Blinking	0F





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02
Display ON cursor Blinking	0F
Address for Line 1	80





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02
Display ON cursor Blinking	0F
Address for Line 1	80
Address for Line 2	C0





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02
Display ON cursor Blinking	0F
Address for Line 1	80
Address for Line 2	C0
Display ON cursor OFF	0C





Description	Hex
Function set (8-bit interface, 2 lines, 5*7 Pixels)	38
Function set (4-bit interface, 2 lines, 5*7 Pixels)	28
Clear display screen	01
Return Home (First line first block)	02
Display ON cursor Blinking	0F
Address for Line 1	80
Address for Line 2	C0
Display ON cursor OFF	0C





### Steps for LCD Initialization





1 Initialize PortC as Output Port





- Initialize PortC as Output Port
- 2 Set Control Lines i.e. RS=0 and RW=0





- Initialize PortC as Output Port
- 2 Set Control Lines i.e. RS=0 and RW=0
- 3 Send LCD init value i.e. 0x38 for 8-bit mode OR 0x28 for 4-bit mode





- Initialize PortC as Output Port
- Set Control Lines i.e. RS=0 and RW=0
- 3 Send LCD init value i.e. 0x38 for 8-bit mode OR 0x28 for 4-bit mode
- Generate High-Low Pulse on Enable Pin of LCD







- Initialize PortC as Output Port
- Set Control Lines i.e. RS=0 and RW=0.
- Send LCD init value i.e. 0x38 for 8-bit mode OR 0x28 for 4-bit mode
- Generate High-Low Pulse on Enable Pin of LCD
- Send LCD Clear value i.e. 0x01





- Initialize PortC as Output Port
- 2 Set Control Lines i.e. RS=0 and RW=0
- Send LCD init value i.e. 0x38 for 8-bit mode OR 0x28 for 4-bit mode
- Generate High-Low Pulse on Enable Pin of LCD
- Send LCD Clear value i.e. 0x01
- **6** Send LCD Display On value i.e. 0x0F





- Initialize PortC as Output Port
- 2 Set Control Lines i.e. RS=0 and RW=0
- Send LCD init value i.e. 0x38 for 8-bit mode OR 0x28 for 4-bit mode
- Generate High-Low Pulse on Enable Pin of LCD
- Send LCD Clear value i.e. 0x01
- Send LCD Display On value i.e. 0x0F
- Send LCD Cursor Home i.e. 0x02





### lcd.h - The header file





#### lcd.h - The header file

1 This file must be copied into Project Folder





#### lcd.h - The header file

1 This file must be copied into Project Folder





This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();
```





1 This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();

// To initialize LCD
void lcd_init();
```





This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();

// To initialize LCD
void lcd_init();

// To send command
void lcd_wr_command(unsigned char cmd);
```





1 This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();

// To initialize LCD
void lcd_init();

// To send command
void lcd_wr_command(unsigned char cmd);

// To write single character
void lcd_wr_char(char row, char column, char alpha_num_char);
```





1 This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();

// To initialize LCD
void lcd_init();

// To send command
void lcd_wr_command(unsigned char cmd);

// To write single character
void lcd_wr_char(char row, char column, char alpha_num_char);

// To print string of characters
void lcd_string(char row, char column, char* str);
```





1 This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();
// To initialize LCD
void lcd_init();
// To send command
void lcd wr command(unsigned char cmd):
// To write single character
void lcd wr char(char row, char column, char alpha num char):
// To print string of characters
void lcd_string(char row, char column, char* str);
// To place cursor at a desired location
void lcd_cursor(char row, char column);
```





This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();
 // To initialize LCD
void lcd_init();
// To send command
void lcd wr command(unsigned char cmd):
 // To write single character
void lcd wr char(char row, char column, char alpha num char):
// To print string of characters
void lcd_string(char row, char column, char* str);
// To place cursor at a desired location
void lcd_cursor(char row, char column);
 // To print numeric values
void lcd_numeric_value(char row,char column, int value, int digits);
```







This file must be copied into Project Folder

```
// Configure the Port where LCD is connected
void lcd_port_config();
 // To initialize LCD
void lcd_init();
// To send command
void lcd wr command(unsigned char cmd):
 // To write single character
void lcd wr char(char row, char column, char alpha num char):
// To print string of characters
void lcd_string(char row, char column, char* str);
// To place cursor at a desired location
void lcd_cursor(char row, char column);
 // To print numeric values
void lcd_numeric_value(char row,char column, int value, int digits);
```







### Syntax for C-Program





# Syntax for C-Program

```
#include
```





## Syntax for C-Program

```
#include
#include <avr/io.h>
#include <util/delay.h>
#include "lcd.h" // User-defined header file
```





## Syntax for C-Program

```
#include
#include <avr/io.h>
#include <util/delay.h>
#include "lcd.h" // User-defined header file
```

#### Main Program





www.e-yantra.org

## Syntax for C-Program

```
#include
#include <avr/io.h>
#include <util/delay.h>
#include "lcd.h" // User-defined header file
```

```
Main Program
int main (void)
{
    lcd_port_config();
    lcd_init();
    lcd_string(1, 3, "e-Yantra");
    lcd_string(2, 3, "IIT Bombay");
    _delay_ms(5000);
    lcd_clear();
    lcd_numeric_value(2, 6, 458, 4);
    while(1);
```

www.e-yantra.org





Some Important commands LCD Initialization Programming

### Thank You!

Post your queries on: support@e-yantra.org



