

# Sheikh Hasina University, Netrokona Department of Computer Science and Engineering

**CSE-2205: Introduction to Mechatronics** 

**Lec-3: Displacement Sensors** 

Md. Ariful Islam

**Assistant Professor** 

Dept. of Robotics and Mechatronics Engineering
University of Dhaka

&

**Adjunct Faculty** 

Sheikh Hasina University, Netrokona

Department of Computer Science and Engineering


# Contents

Displacement Sensors	2
Potentiometer	2
Linear variable differential transformer (LVDT)	4

# **Displacement Sensors**

## Potentiometer

A potentiometer consists of a resistance element with a sliding contact which can be moved over the length of the element. Such elements can be used for linear or rotary displacements; the displacement being converted into a potential difference. The rotary potentiometer consists of a circular wire-wound track or a film of conductive plastic over which a rotatable sliding contact can be rotated (Figure). The track may be a single turn or helical.



With a constant input voltage Vs between terminals 1 and 3, the output voltage Vo between terminals 2 and 3 is a fraction of the input voltage, the fraction depending on the ratio of the resistance  $R_{23}$  between terminals 2 and 3 compared with the total resistance  $R_{13}$  between terminals 1 and 3, i.e.  $V_o > V_s = R_{23} > R_{13}$ . If the track has a constant resistance per unit length, i.e. per unit angle, then the output is proportional to the angle through which the slider has rotated. Hence an angular displacement can be converted into a potential difference.

With a wire-wound track the slider in moving from one turn to the other will change the voltage output in steps, each step being a movement of one turn. If the potentiometer has N turns then the resolution, as a percentage, is 100/N. Thus the resolution of a wire track is limited by the diameter of the wire used and typically ranges from about 1.5 mm for a coarsely wound track to 0.5 mm for a finely wound one. Errors due to non-linearity of the track tend to range from less than 0.1% to about 1%. The track resistance tends to range from about 20  $\Omega$  to 200  $\Omega$ . Conductive plastic has ideally infinite resolution, errors due to non-linearity of the track of the order of 0.05% and resistance values from about 500  $\Omega$  to 80 k $\Omega$ . The conductive plastic has a higher temperature coefficient of resistance than the wire and so temperature changes have a greater effect on accuracy.

An important effect to be considered with a potentiometer is the effect of a load RL connected across the output. The potential difference across the load  $V_L$  is only directly proportional to  $V_0$  if the load resistance is infinite. For finite loads, however, the effect of the load is to transform what was a linear relationship between output voltage and angle into a non-linear relationship.

The resistance RL is in parallel with the fraction x of the potentiometer resistance  $R_P$ . This combined resistance is  $R_L \times R_p > (R_L + x R_p)$ . The total resistance across the source voltage is thus

total resistance = 
$$R_p(1 - x) + R_L x R_p / (R_L + x R_p)$$

The circuit is a potential divider circuit and thus the voltage across the load is the fraction that the resistance across the load is of the total resistance across which the applied voltage is connected:

$$\frac{V_{\rm L}}{V_{\rm s}} = \frac{xR_{\rm L}R_{\rm p}/(R_{\rm L} + xR_{\rm p})}{R_{\rm p}(1-x) + xR_{\rm L}R_{\rm p}/(R_{\rm L} + xR_{\rm p})}$$
$$= \frac{x}{(R_{\rm p}/R_{\rm L})x(1-x) + 1}$$

If the load is of infinite resistance, then we have  $V_L = xV_s$ . Thus the error introduced by the load having a finite resistance is


error = 
$$xV_{\rm s} - V_{\rm L} = xV_{\rm s} - \frac{xV_{\rm s}}{(R_{\rm p}/R_{\rm L})x(1-x)+1}$$
  
=  $V_{\rm s} \frac{R_{\rm p}}{R_{\rm L}} (x^2 - x^3)$ 

To illustrate the above, consider the non-linearity error with a potentiometer of resistance 500  $\Omega$  when at a displacement of half its maximum slider travel, which results from there being a load of resistance 10  $k\Omega$ . The supply voltage is 4 V. Using the equation derived above

error = 
$$4 \times \frac{500}{10,000} (0.5^2 - 0.5^3) = 0.025 \text{ V}$$

As a percentage of the full range reading, this is 0.625%.

Potentiometers are used as sensors in automobiles, being used for such things as the fuel-level sensor and accelerator pedal sensor. Figure shows how, for a fuel-level sensor, a float lever system is used to rotate the wiper arm of a potentiometer and give a voltage output which is a measure of the fuel level.



# Linear variable differential transformer (LVDT)

**LVDT** is an acronym for Linear Variable Differential Transformer. It is a common type of electromechanical transducer that can convert the rectilinear motion of an object to which it is coupled mechanically into a corresponding electrical signal. LVDT linear position sensors are readily available that can measure movements as small as a few millionths of an inch up to several inches, but are also capable of measuring positions up to ±30 inches (±0.762 meter). Figure 1 shows the components of a typical LVDT. The transformer's internal structure consists of a primary winding centered between a pair of identically wound secondary windings, symmetrically spaced about the primary. The coils are wound on a one-piece hollow form of thermally stable glass reinforced polymer, encapsulated against moisture, wrapped in a high permeability magnetic shield, and then secured in a cylindrical stainless steel housing. This coil assembly is usually the stationary element of the position sensor.




FIGURE: The primary winding is illustrated in the center of the LVDT. Two secondary coils are wound symmetrically on each side of the primary coil as shown for "short stroke" LVDTs or on top of the primary coil for "long stroke" LVDTs. The two secondary windings are typically connected in "series opposing" (Differential).

The moving element of an LVDT is a separate tubular armature of magnetically permeable material. This is called the core, which is free to move axially within the coil's hollow bore, and mechanically coupled to the object whose position is being measured. This bore is typically large enough to provide substantial radial clearance between the core and bore, with no physical contact between it and the coil. In operation, the LVDT's primary winding is energized by alternating current of appropriate amplitude and frequency, known as the primary excitation. The LVDT's electrical output signal is the differential AC voltage between the two secondary windings, which varies with the axial position of the core within the LVDT coil. Usually this AC output voltage is converted by suitable electronic circuitry to high level DC voltage or current that is more convenient to use.

#### How Does an LVDT Work?

Figure illustrates what happens when the LVDT's core is in different axial positions. The LVDT's primary winding, P, is energized by a constant amplitude AC source. The magnetic flux thus developed is coupled by the core to the adjacent secondary windings, S1 and S2. If the core is located midway between S1 and S2, equal flux is coupled to each secondary so the voltages, E1 and E2, induced in windings S1 and S2 respectively, are equal. At this reference midway core position, known as the null point, the differential voltage output, (E1 - E2), is essentially zero. As shown in Figure 2, if the core is moved closer to S1 than to

S2, more flux is coupled to S1 and less to S2, so the induced voltage E1 is increased while E2 is decreased, resulting in the differential voltage (E1 - E2). Conversely, if the core is moved closer to S2, more flux is coupled to S2 and less to S1, so E2 is increased as E1 is decreased, resulting in the differential voltage (E2 - E1).





FIGURE: Illustrates what happens when the LVDT's core is in different axial positions.

Figure shows how the magnitude of the differential output voltage, EOUT, varies with core position. The value of EOUT at maximum core displacement from null depends upon the amplitude of the primary excitation voltage and the sensitivity factor of the particular LVDT, but is typically several volts RMS.



# Why Use an LVDT?

#### **Friction-Free Operation**

One of the most important features of an LVDT is its friction-free operation. In normal use, there is no mechanical contact between the LVDT's core and coil assembly, so there is no rubbing, dragging, or other source of friction. This feature is particularly useful in materials testing, vibration displacement measurements, and high resolution dimensional gaging systems.

#### **Infinite Resolution**

Since an LVDT operates on electromagnetic coupling principles in a friction-free structure, it can measure infinitesimally small changes in core position. This infinite resolution capability is limited only by the noise in an LVDT signal conditioner and the output display's resolution. These same factors also give an LVDT its outstanding repeatability.

#### **Unlimited Mechanical Life**

Because there is normally no contact between the LVDT's core and coil structure, no parts can rub together or wear out. This means that an LVDT features unlimited mechanical life. This factor is especially important in high reliability applications such as aircraft, satellites and space vehicles, and nuclear installations. It is also highly desirable in many industrial process control and factory automation systems.

#### **Over travel Damage Resistant**

The internal bore of most LVDTs is open at both ends. In the event of unanticipated overtravel, the core is able to pass completely through the sensor coil assembly without causing damage. This invulnerability to position input overload makes an LVDT a suitable sensor for applications like extensometers that are attached to tensile test samples in destructive materials testing apparatus.

## **Single Axis Sensitivity**

An LVDT responds to motion of the core along the coil's axis, but is generally insensitive to cross-axis motion of the core or to its radial position. Thus, an LVDT can usually function without adverse effect in applications involving misaligned or floating moving members, and in cases where the core does not travel in a precisely straight line.

#### **Separable Coil and Core**

Because the only interaction between an LVDT's core and coil is magnetic coupling, the coil assembly can be isolated from the core by inserting a non-magnetic tube between the core and the bore. By doing so, a pressurized fluid can be contained within the tube, in which the core is free to move, while the coil assembly is unpressurized. This feature is often utilized in LVDTs used for spool position feedback in hydraulic proportional and/or servo valves.

#### **Environmentally Robust**

The materials and construction techniques used in assembling an LVDT result in a rugged, durable sensor that is robust to a variety of environmental conditions. Bonding of the windings is followed by epoxy encapsulation into the case, resulting in superior moisture and humidity resistance, as well as the capability to take substantial shock loads and high vibration levels in all axes. And the internal high-permeability magnetic shield minimizes the effects of external AC fields. Both the case and core are made of corrosion resistant metals, with the case also acting as a supplemental magnetic shield. And for those applications where the sensor must withstand exposure to flammable or corrosive vapors and liquids, or operate in pressurized fluid, the case and coil assembly can be hermetically sealed using a variety of welding processes. Ordinary LVDTs can operate over a very wide temperature range, but, if required, they can be produced to operate down to cryogenic temperatures, or, using special materials, operate at the elevated temperatures and radiation levels found in many nuclear reactors.

#### **Null Point Repeatibility**

The location of an LVDT's intrinsic null point is extremely stable and repeatable, even over its very wide operating temperature range. This makes an LVDT perform well as a null position sensor in closed-loop control systems and high-performance servo balance instruments.

#### **Fast Dynamic Response**

#### Sensors

The absence of friction during ordinary operation permits an LVDT to respond very fast to changes in core position. The dynamic response of an LVDT sensor itself is limited only by the inertial effects of the core's slight mass. More often, the response of an LVDT sensing system is determined by characteristics of the signal conditioner.

## **Absolute Output**

An LVDT is an absolute output device, as opposed to an incremental output device. This means that in the event of loss of power, the position data being sent from the LVDT will not be lost. When the measuring system is restarted, the LVDT's output value will be the same as it was before the power failure occurred.