

Bend at 100° Gluing first and then drill to M2 73	
---	--

	NAME	SIGN	DATE	
DRW BY	IRONY			EMU
CHK BY	E. AKBIL			
SCALE 1/1	Upper Arm Link 2			DWG NO 1.2.4